

REFERENCE NUMBER: HMT-0102-00-E SUBJECT: Recall #32 PSeriesOperator's Manual v3.1, Manual Storage, Capacity Chart and Wall Tie Chart stickers EFFECTIVE DATE: October 15th ,2005 APPLICABLE SERIES: P APPLICABLE SERIAL NUMBERS: PU0001 to PU0200

Operator's manuals included with units shipped out prior to this recall are not complete and must be recalled. All P Series Operator's manuals prior to version 3.1 must be replaced. This latest version (v 3.1) contains more detailed and accurate information. Also included in the present recall are panels displaying the capacity chart sticker and the wall tie schedule as required by OSHA regulation. This recall also includes a waterproof storage container for the Operator's manual. Failure to perform this recall could result in serious injuries or death.

This recall can be performed as follows:

1- For all P Series motorized units with serial # PU0001 to PU0104

- Aluminum panel displaying the capacity chart and the wall tie schedule sticker must be installed on the guardrail.
- The Operator's manual storage container including version 3.1 of the manual must be installed on the motorized unit.
- Recuperate old Operator's manuals prior to version 3.1.
- Fill recall completion form and send it back Hydro Mobile's offices.

- The Operator manual storage container including version 3.1 of the manual must be installed.
- The wall tie chart sticker on the aluminum panel must be replaced with the new version 2.
- Recuperate old Operator's manuals prior to version 3.1.
- Fill recall completion form and send it back Hydro Mobile's offices.



During this recall, Hydro Mobile distributors must recuperate all Operator's manuals prior to version 3.1 and have them available for their regional manager to pick up. The Recall Completion form must be filled out and returned to Hydro Mobile offices. The procedure and material pertaining to the recall are attached herein.

Upon additional request, Hydro Mobile will provide the material to perform the recall on other P Series motorized units for every unit serial number submitted. Hydro Mobile will also credit ¼ hour at our regular warranty rate of 50\$/hour of labor for each retrofitted P Series motorized unit upon return of the **Recall Completion** form. Note that travel time expenses will not be subject to reimbursement. Hydro Mobile will issue a one-time credit once all units have been retrofitted and all Recall Completion forms have been returned to Hydro Mobile's Canadian offices.

We truly regret any inconvenience this situation may have caused. We would appreciate any comments or questions you may have regarding this recall. Our Customer Service representatives can be reached toll free at 1-888-484-9376.

Installation Procedure

Part required for recall:

- For P Series motorized units with serial # PU0001 to PU0104
 - 1x aluminium panel with sticker kit part # 30002100-k-01000-0
 - 1x Operator's manual kit with storage container part # 30019500-k-01000-4

For P Series motorized units with serial # PU0105 to PU0200


- 1x Operator manual kit with storage container part # 30019500-k-01000-4
- 1x wall tie schedule sticker version 2 part # A08000000-0030

Tools required for installation:

-Cordless drill with #2 Robertson (square) bit. -Regular (flat) screw driver.

Installation procedure for the aluminum panel (capacity chart sticker):

The plate will have to be bolted on by the customer on the back guardrail of the P Series extension platform. Install the aluminum plate outside of the guardrail as shown hereafter with 5x self-tapping screws. The plate must be installed so the chart is facing inward and the Hydro Mobile logo facing outward.



Procedure for the installation of version 2 of the wall tie schedule sticker

On P Series motorized units already equipped with an aluminum panel, paste the new version #2 wall tie schedule sticker on top of the old one.


Procedure for the installation of the Operator's manual storage container :

The Operator's manual storage container attachment bracket will have to be mounted on the $4x^2$ rectangular tube as shown on the picture below with 4 self-tapping screws. Then, use the clamp to




fix the container in place. Replace any older version of the manual with version 3.1 of the Operator's manual. Recuperate old version of Operator's manual.

Location of toolbox on power unit



Position Toolbox bracket $1\frac{1}{2}$ " from the bottom tube and fasten using 4 self tapping screw supplied.



Install Toolbox tube on bracket using hose clamp



OBJECT OF RECALL:

P Series Operator's Manual v3.1, Manual storage, Capacity Chart and Wall tie chart stickers

This confirms that the P Series Operator's Manual v3.1, Manual storage Capacity Chart and Wall tie chart stickers recall has been performed on the following motorized unit:

P Series unit serial number	P-
Date	
Distributor	
Unit owner	
Recall performed by	
	Yes No
Operators manual storage has installed	
Aluminum panel has been inst	alled
New wall tie schedule sticker h been installed	as
Old version of Operator's Man has been recuperated	

NOTE: This Recall Completion form must be filled out and returned to Hydro Mobile offices.



RECALL

Re:	P Series Operator's Manual v3.1, Manual Storage, Capacity Chart and Wall Tie Chart stickers
No :	Recall #32
Date:	December 19 th -2005
From:	R&D and Engineering Department
Cc:	Regional Managers & Marketing Department
To:	Distributor Network

Operator's manuals included with units shipped out prior to this recall are not complete and must be recalled. All P Series Operator's manuals prior to version 3.1 must be replaced. This latest version (v 3.1) contains more detailed and accurate information. Also included in the present recall are panels displaying the capacity chart sticker and the wall tie schedule as required by OSHA regulation. This recall also includes a waterproof storage container for the Operator's manual. Failure to perform this recall could result in serious injuries or death.

This recall can be performed as follows:

1- For all P Series motorized units with serial # PU0001 to PU0104

- Aluminum panel displaying the capacity chart and the wall tie schedule sticker must be installed on the guardrail.
- The Operator's manual storage container including version 3.1 of the manual must be installed on the motorized unit.
- Recuperate old Operator's manuals prior to version 3.1.
- Fill recall completion form and send it back Hydro Mobile offices.

- The Operator manual storage container including version 3.1 of the manual must be installed.
- The wall tie chart sticker on the aluminum panel must be replaced with the new version 2.
- Recuperate old Operator's manuals prior to version 3.1.
- Fill recall completion form and send it back Hydro Mobile offices.



During this recall, Hydro Mobile distributors must recuperate all Operator's manuals prior to version 3.1 and have them available for their regional manager to pick up. The Recall Completion form must be filled out and returned to Hydro Mobile offices. The procedure and material pertaining to the recall are attached herein.

Upon additional request, Hydro Mobile will provide the material to perform the recall on other P Series motorized units for every unit serial number submitted. Hydro Mobile will also credit ¼ hour at our regular warranty rate of 50\$/hour of labor for each retrofitted P Series motorized unit upon return of the **Recall Completion** form. Note that travel time expenses will not be subject to reimbursement. Hydro Mobile will issue a one-time credit once all units have been retrofitted and all Recall Completion forms have been returned to Hydro Mobile's Canadian offices.

We truly regret any inconvenience this situation may have caused. We would appreciate any comments or questions you may have regarding this recall. Our Customer Service representatives can be reached toll free at 1-888-484-9376.

Installation Procedure

Parts required for recall:


- For P Series motorized units with serial # PU0001 to PU0104
 - 1x aluminium panel with sticker kit part # 30002100-k-01000-0
 - 1x Operator's manual kit with storage container part # 30019500-k-01000-4
- For P Series motorized units with serial # PU0105 to PU0200
 - 1x Operator's manual kit with storage container part # 30019500-k-01000-4
 - 1x wall tie schedule sticker version 2 part # A0800000-0030

Tools required for installation:

-Cordless drill with #2 Robertson (square) bit. -Regular (flat) screwdriver.

Installation procedure for the aluminum panel (capacity chart sticker):

The plate will have to be bolted on the back guardrail of the P Series extension platform. Install the aluminum plate outside of the guardrail as shown hereafter with 5x self-tapping screws. The plate must be installed so the chart is facing inward and the Hydro Mobile logo facing outward.



Procedure for the installation of version 2 of the wall tie schedule sticker


On P Series motorized units already equipped with an aluminum panel, paste the new version #2 wall tie schedule sticker on top of the old one.

Procedure for the installation of the Operator's manual storage container-:




The Operator's manual storage container attachment bracket will have to be mounted on the 4x2 rectangular tube as shown on the picture below with 4 self-tapping screws. Then, use the clamp to fix the container in place. Replace any older version of the manual with version 3.1 of the Operator's manual. Recuperate old version of Operator's manual.

Location of manual storage container on motorized unit



Position manual storage container bracket -11/2" from bottom tube and fasten using 4 self tapping screws supplied.





Install manual storage container on bracket using hose clamp





To: Distributors' Network

From: R&D and Engineering Department

CC: Regional Managers and Marketing Department

RECALL NO.: 32

Date: May 5th 2006

Subject: <u>Second notice</u> for **P** Series Operator's Manual v3.1, Manual Storage, Capacity Chart and Wall Tie Chart stickers

This is a second notice to remind you that this recall is very important and must be performed right away. Please note that you must return the recall completion form in order to confirm that this recall has been performed. All parts to perform this recall have been sent to distributor in December 2005.

Operator's manuals included with units shipped out prior to this recall are not complete and must be recalled. All P Series Operator's manuals prior to version 3.1 must be replaced. This latest version (v 3.1) contains more detailed and accurate information. Also included in the present recall are panels displaying the capacity chart sticker and the wall tie schedule as required by OSHA regulation. This recall also includes a waterproof storage container for the Operator's manual. Failure to perform this recall could result in serious injuries or death.

This recall can be performed as follows:

1- For all P Series motorized units with serial # PU0001 to PU0104

- Aluminum panel displaying the capacity chart and the wall tie schedule sticker must be installed on the guardrail.
- The Operator's manual storage container including version 3.1 of the manual must be installed on the motorized unit.
- Recuperate old Operator's manuals prior to version 3.1.
- Fill recall completion form and send it back Hydro Mobile offices.

- The Operator manual storage container including version 3.1 of the manual must be installed.
- The wall tie chart sticker on the aluminum panel must be replaced with the new version 2.
- Recuperate old Operator's manuals prior to version 3.1.
- Fill recall completion form and send it back Hydro Mobile offices.



During this recall, Hydro Mobile distributors must recuperate all Operator's manuals prior to version 3.1 and have them available for their regional manager to pick up. The Recall Completion form must be filled out and returned to Hydro Mobile offices. The procedure and material pertaining to the recall are attached herein.

Upon additional request, Hydro Mobile will provide the material to perform the recall on other P Series motorized units for every unit serial number submitted. Hydro Mobile will also credit ¼ hour at our regular warranty rate of 50\$/hour of labor for each retrofitted P Series motorized unit upon return of the **Recall Completion** form. Note that travel time expenses will not be subject to reimbursement. Hydro Mobile will issue a one-time credit once all units have been retrofitted and all Recall Completion forms have been returned to Hydro Mobile's Canadian offices.

We truly regret any inconvenience this situation may have caused. We would appreciate any comments or questions you may have regarding this recall. Our Customer Service representatives can be reached toll free at 1-888-484-9376.



To: Distributors' Network

From: R&D and Engineering Department

CC: Regional Managers and Marketing Department

Date: July 13th 2007

Subject: <u>Final notice</u> for **P** Series Operator's Manual v3.1, Manual Storage, Capacity Chart and Wall Tie Chart stickers

This is the third notice to remind you that this recall is very important and must have beed performed by now. Please note that you must return the recall completion form in order to confirm that this recall has been performed. All the parts to perform this recall have been sent to distributors in December 2005.

For this recall to be eligible for a labor reimbursement, all Recall Completion forms must be returned to Hydro Mobile offices before August 15th 2007.

Problem description

Operator's manuals included with units shipped out prior to this recall are not complete and must be recalled. All P Series Operator's manuals prior to version 3.1 must be replaced. This latest version (v 3.1) contains more detailed and accurate information. Also included in the present recall are panels displaying the capacity chart sticker and the wall tie schedule as required by OSHA regulation. This recall also includes a waterproof storage container for the Operator's manual. Failure to perform this recall could result in serious injuries or death.

This recall can be performed as follows:

1- For all P Series motorized units with serial # PU0001 to PU0104

- Aluminum panel displaying the capacity chart and the wall tie schedule sticker must be installed on the guardrail.
- The Operator's manual storage container including version 3.1 of the manual must be installed on the motorized unit.
- Recuperate old Operator's manuals prior to version 3.1.
- Fill recall completion form and send it back Hydro Mobile offices.

- The Operator manual storage container including version 3.1 of the manual must be installed.
- The wall tie chart sticker on the aluminum panel must be replaced with the new version 2.
- Recuperate old Operator's manuals prior to version 3.1.
- Fill recall completion form and send it back Hydro Mobile offices.




During this recall, Hydro Mobile distributors must recuperate all Operator's manuals prior to version 3.1 and have them available for their regional manager to pick up. The Recall Completion form must be filled out and returned to Hydro Mobile offices.

Upon additional request, Hydro Mobile will provide the material to perform the recall on other P Series motorized units for every unit serial number submitted. Hydro Mobile will also credit ¼ hour at our regular warranty rate of 50\$/hour of labor for each retrofitted P Series motorized unit upon return of the **Recall Completion** form before December 1st 2006. Note that travel time expenses will not be subject to reimbursement. Hydro Mobile will issue a one-time credit once all units have been retrofitted and all Recall Completion forms have been returned to Hydro Mobile's Canadian offices.

We truly regret any inconvenience this situation may have caused. We would appreciate any comments or questions you may have regarding this recall. Our Customer Service representatives can be reached toll free at 1-888-484-9376.



















HYDRO MOBILE 1.888.484.9376













